



AEI Consultants

February 23, 2018

CORRECTIVE MEASURES IMPLEMENTATION

LOT 1102, 180 MILL STREET, CRANSTON, RHODE ISLAND

VOLUME I

Property Identification:

BASF Former Ciba-Geigy Facility

180 Mill Street

Cranston, Rhode Island

AEI Project No. 363655



Prepared for:

BASF Corporation

100 Park Avenue

Florham Park, New Jersey 07932

Prepared by:

AEI Consultants

112 Water Street, 5th Floor

Boston, Massachusetts 02109

Gordon R. Archibald, Inc.

200 Main Street

Pawtucket, Rhode Island

San Francisco HQ

Atlanta

Boston

Chicago

Costa Mesa

Dallas

Denver

Los Angeles

Miami

New York

Phoenix

Portland

San Jose



SEMS DocID

643696

AEI
Consultants

TABLE OF CONTENTS

Volume I

Title	Tab
Corrective Measures Implementation Work Plan.....	1
2017 Subsurface Test Pitting Program Technical Memorandum	A
2017 Groundwater Sampling Technical Memorandum.....	B
July 2017 Risk Assessment/Conceptual Site Model/Preliminary Design Memorandum.....	C
Human Health Risk Evaluation	D
Final Remedial Design	E
Template Environmental Land Usage Restriction	G
Template Soil and Groundwater Management Plan.....	H
Soil Erosion and Sediment Control Plan.....	I
Clean Soil Cover Inspection and Maintenance Plan	J
Health and Safety Plan	K

Volume II

Title	Tab
Appendix F – Sampling and Analysis Plan (SAP)/Quality Assurance Project Plan (QAPP).....	F



AEI Consultants

February 23, 2018

**CORRECTIVE MEASURES IMPLEMENTATION WORK PLAN:
Soil Remedy for Former Production Area (Lot 1102)**

San Francisco HQ

Atlanta

Boston

Chicago

Costa Mesa

Dallas

Denver

Los Angeles

Miami

New York

Phoenix

Portland

San Jose

Property Identification:

BASF Former Ciba-Geigy Facility
180 Mill Street
Cranston, Rhode Island
AEI Project No. 363655



Prepared for:

BASF Corporation
100 Park Avenue
Florham Park, New Jersey 07932

Prepared by:

AEI Consultants
112 Water Street, 5th Floor
Boston, Massachusetts 02109

Gordon R. Archibald, Inc.
200 Main Street
Pawtucket, Rhode Island

AEI
Consultants

Corrective Measures Implementation Work Plan
February 23, 2018

BASF Former Ciba-Geigy Facility
180 Mill Street, Cranston, Rhode Island


Prepared By:



Aaron C. Ting, PE
Project Engineer, AEI Consultants



Richard G. Kowalski, CPG, LSP, CHMM
Senior Hydrogeologist/Project Manager, AEI Consultants



Stephen J. Graham, PE, LSP
Senior Vice President/Principal, AEI Consultants



Steven P. Cadorette, P.E.,
Senior Civil Engineer/Lead Design Engineer, Gordon R. Archibald, Inc.



TABLE OF CONTENTS

1.0	BACKGROUND	1
2.0	INTRODUCTION.....	6
2.1	Purpose and Objectives	7
2.2	Work Plan Overview	9
2.3	Program Management.....	10
3.0	SITE DESCRIPTION AND ENVIRONMENTAL ISSUES	11
3.1	Site History and Usage	11
3.2	Geologic and Hydrogeologic Setting.....	11
3.3	Previous Investigations and Remedial Actions.....	12
3.3.1	1990 to 1994 RCRA Facility Investigation [RFI] (Ciba Corporation, 1995)	12
3.3.2	1995 Pawtuxet River Sediment RFI	13
3.3.3	1995 Interim Remedial Measure [IRM] (Woodward-Clyde, 1996).....	13
3.3.4	1996 Groundwater Treatment System (AECOM, 2016b).....	14
3.3.5	1997 Soil Vapor Extraction [SVE]/Pre-Design Investigation [PDI], presented in final CMS (AECOM, 2016a)	14
3.3.6	2014 Supplemental Remedial Investigation [SRI] (AECOM, 2016b).....	15
3.3.7	May 2016 Draft Statement of Basis (EPA, 2016).....	16
3.3.8	May 2017 Subsurface Investigation (AEI, 2017b)	16
3.3.9	April 2017 Groundwater Monitoring (AEI, 2017c)	17
3.3.10	July 2017 Conceptual Site Model and Risk Evaluation (AEI, 2017a).....	17
3.4	Nature and Extent of Contamination	18
3.4.1	PCBs and VOCs in Soil	18
3.4.2	Deep and Shallow Groundwater.....	19
3.5	Cleanup Standards	19
3.5.1	Remedial Objectives	19
3.5.2	Soil Objectives	20
3.5.3	Groundwater Objectives.....	20
4.0	CORRECTIVE MEASURES IMPLEMENTATION DESIGN.....	22
4.1	Design Scope.....	22
4.2	Soil Remedial Approach	22

4.2.1	Soil Remedial Measure	25
4.2.1.1	Site Preparation and Pre-Excavation Planning	25
4.2.1.2	ISCO Ozone Pilot Test Pad.....	25
4.2.1.3	Removal of PCB-Impacted Soils.....	26
4.2.1.4	Removal of VOC-Impacted Soils	27
4.2.1.5	Concrete and Debris.....	28
4.2.1.6	De-Watering.....	29
4.2.1.7	Soil Management	29
4.2.1.8	Post Excavation Verification Sampling	30
4.2.1.9	Backfill	31
4.2.2	Clean Soil Cover	31
4.2.3	ELUR.....	33
4.2.4	Groundwater Remedial Approach.....	33
4.2.4.1	Residual Upland Groundwater Contamination	34
4.2.4.2	COC Migration Control.....	34
5.0	CORRECTIVE MEASURES IMPLEMENTATION AND CONSTRUCTION PLANS	35
5.1	Permitting	35
5.2	Community Relations Plan	36
5.3	Pre-Construction Activities	37
5.4	Contractor Standards – Soil Remedy.....	38
5.4.1	Contract Drawings and Design Specifications	38
5.4.2	Set-up Plans	40
5.4.3	Contingency Plan.....	40
5.4.4	Health and Safety.....	41
5.5	Construction	41
5.5.1	Storm Water and Erosion Controls	41
5.5.2	Site Traffic Management	41
5.5.3	Soil Excavations	42
5.5.4	Waste Handling, Transportation and Disposal	43
5.5.5	Clean Soil Covering.....	43

5.6	Shutdown.....	44
6.0	OPERATION AND MAINTENANCE	45
6.1	Clean Soil Cover Inspection and Maintenance.....	45
6.2	Sediment Monitoring	45
6.3	ISCO Progress Monitoring.....	45
7.0	SCHEDULE AND REPORTING.....	46
7.1	Project Schedule.....	46
7.2	Reporting	46
7.2.1	Closure and Post-Closure Reporting	47
8.0	REFERENCES	48
9.0	CERTIFICATION STATEMENTS	49

List of Figures

- Figure 1 – Site Survey Map
- Figure 2 – General Site Plan
- Figure 3 – PCB Groundwater Analytical Results
- Figure 4 – PCB Shallow Soil Impacts

List of Tables

- Table 1 – SRI PCB Groundwater Analytical Results
- Table 2 – Proposed Remedial Schedule

List of Attachments

- Attachment 1 – EPA’s Draft Statement of Basis
- Attachment 2 – PCB Soil Data Tables for Lot 1102
- Attachment 3 – PCB Analysis Comparability Study and PCB Analysis Using Dexsil Method Standard Operating Procedure
- Attachment 4 – PCB Soil Data Tables for Lots 1108 and 2630

Appendices

- Appendix A – 2017 Subsurface Test Pitting Program Technical Memorandum
- Appendix B – 2017 Groundwater Sampling Technical Memorandum
- Appendix C – July 2017 Risk Assessment/Conceptual Site Model/Preliminary Design Memorandum
- Appendix D – Human Health Risk Evaluation
- Appendix E – Final Remedial Design
- Appendix F – Sampling and Analysis Plan (SAP)/Quality Assurance Project Plan (QAPP)

- Appendix G – Template Environmental Land Usage Restriction
- Appendix H – Template Soil and Groundwater Management Plan
- Appendix I – Soil Erosion and Sediment Control Plan
- Appendix J – Clean Soil Cover Inspection and Maintenance Plan
- Appendix K – Health and Safety Plan